

Attorney Docket No. 392.1858
IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

002 1050

In re Patent Application of:

Yukio TOYOZAWA, et al.

Application No.: 10/753,409

Confirmation No.: 6401

Filed: January 9, 2004

U.S. Patent No.: 6,903,527

Issued: June 7, 2005

For:

SERVO CONTROLLER

ATTENTION

CERTIFICATE OF CORRECTION

BRANCH

Batch No.: B2

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents PO Box 1450 Alexandria, VA 22313-1450

Sir:

Patentee(s) respectfully request(s) that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistake(s) shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY LLP

Data

Jan. 17, 200 C

D.

H. J. Staas

Registration No. 22,010

1201 New York Ave, N.W., Suite 700

Washington, D.C. 20005 Telephone: (202) 434-1500 Facsimile: (202) 434-1501

Certificate
JAN 2 0 2006

of Correction

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : 6,903,527 β^2

DATED: June 7, 2005

INVENTOR(S): Yukio TOYOZAWA, et al.

Column 10, Line 52, after "claim 1" delete ","

MAILING ADDRESS OF SENDER: STAAS & HALSEY LLP 1201 New York Ave., N.W. Suite 700

Washington, DC 20005

PATENT NO. 6,903,527

No. of add'l copies @ 50¢ per page